

SPABOND 820HTA FAST CURING STRUCTURAL EPOXY ADHESIVE

- Long working time for manufacture of large components
- ¬ Suitable for High Temperature Application (HTA) up to 40°C
- Rapid cure in 2 hours at 70°C or 1 hour at 80°C allows reduced cycle time
- ¬ Formulated with Gurit LRT (Light Reflective Technology) as standard
- ¬ Low Toxicity Formulation: Improved Hazard Labelling, CMR & SVHC* Free
- ¬ Excellent gap filling properties of up to 35mm
- Designed for mixing machine dispense to minimise back pressure & maximise dispense rates
- DNV-GL certification pending

INTRODUCTION

Spabond 820HTA is a high performance, glass filled adhesive designed for bonding large structures such as wind turbine blades. It is a cost-effective system with good thermal, mechanical properties with a long working time for adhesive application and incorporates innovative chemistry to allow a rapid cure time at elevated temperature.

The unique formulation offers improved health & safety through the careful selection of low toxicity raw materials as well as Light Reflective Technology which in conjunction with a UV light-source can detect droplets as small as 1mm for easy identification of contamination to improve industrial hygiene or for the inspection of bond-lines to ensure constant quality and reliability of components.

The components are contrasting colours to give a visual indication of mix quality, which is a useful feature when mixing by hand or with a machine. Spabond 820HTA is available in straight-sided 25L and 205L drums for machine dispense using static or dynamic mixing.

* CMR = Substances classified as Carcinogenic, Mutagenic or toxic for Reproduction, SVHC = Substances of Very High Concern

PDS-Spabond820HTA-3-0921 1

PRODUCT INFORMATION

The product is available in a number of formats please contact your local customer support or download the latest product catalogue available on www.gurit.com.

PRODUCT DESCRIPTION	STATUS	CERTIFICATION
Spabond 820 Resin and 820HTA Hardener	Certified	DNV-GL TA-DNVGL-CP-0086-07628-0

TRANSPORT & STORAGE

The resin and hardeners should be kept in securely closed containers during transport and storage. Any accidental spillage should be soaked up with sand, sawdust, cotton waste or any other absorbent material. The area should then be washed clean (see appropriate Safety Data Sheet).

COMPONENT STORAGE TIME	UNITS	10 – 25°C
Spabond 820HTA Resin	months	12
Spabond 820HTA Hardener	months	12

Adequate long term storage conditions will result in a shelf life of 1 year for both the resin and hardeners. Storage should be in a warm dry place out of direct sunlight and protected from frost. The storage temperature should be kept constant between 10°C and 25°C, cyclic fluctuations in temperature can cause crystallization. Containers should be firmly closed. Hardeners, in particular, will suffer serious degradation if left exposed to air. For more information on crystallization please refer to the Adhesives section on the Gurit website.

INSTRUCTIONS FOR USE

The product is optimised for use at 15 - 25°C. At lower temperatures the components thicken and may eventually become unworkable. To ensure accurate mixing and good workability pre-warm the resin & hardener as well as the surfaces to be bonded before use.

SURFACE PREPARATION

Before using the product ensure that surfaces to be bonded are clean, dry and dust-free. Prepare all surfaces by abrading with medium grit paper or other suitable abrasive, remove dust then wipe with acetone.

Metals - requires a chemical pre-treatment to create the best bond. Please contact Gurit for a Guide to Surface Preparation and Pre-treatments.

Polyester or vinylester - ensure laminates are fully cured before bonding, then prepare as above.

Epoxy laminates - it is recommended to use a suitable Peel Ply as the last stage in their manufacture, otherwise prepare as above. Trials may be required to test Peel Ply suitability.

Ferrocement - etch with 5% solution of hydrochloric acid, wash with fresh water, then dry.

Timber - sand with abrasive paper across grain. Degrease oily timber with a fast evaporating solvent (e.g. acetone). For resinous or gummy timber, etch with 2% caustic soda solution, wash off with fresh water and dry.

MIXING & HANDLING

Gurit recommends mixing machine dispense. If mixing by hand, mix thoroughly for at least one minute, paying particular attention to the sides and bottom of the mixing vessel, to ensure no streaks remain. Once fully mixed the adhesive should have a uniform colour. Use from pot quickly to maximise resin working life.

HEALTH AND SAFETY

The following points must be considered:

- 1. Skin contact must be avoided by wearing protective gloves. Gurit recommends the use of disposable nitrile gloves for most applications. The use of barrier creams is not recommended, but to preserve skin condition a moisturising cream should be used after washing.
- 2. Overalls or other protective clothing should be worn when mixing, laminating or sanding. Contaminated work clothes should be thoroughly cleaned before re-use.
- 3. Eye protection should be worn if there is a risk of resin, hardener, solvent or dust entering the eyes. If this occurs flush the eye with water for 15 minutes, holding the eyelid open, and seek medical attention.
- 4. Ensure adequate ventilation in work areas. Respiratory protection should be worn if there is insufficient ventilation. Solvent vapours should not be inhaled as they can cause dizziness, headaches, loss of consciousness and can have long term health effects.
- 5. If the skin becomes contaminated, then the area must be immediately cleansed. The use of resin-removing cleansers is recommended. To finish, wash with soap and warm water. The use of solvents on the skin to remove resins etc must be avoided. Washing should be part of routine practice:
 - before eating or drinking
 - before smoking
 - before using the lavatory
 - ¬ after finishing work
- 6. The inhalation of sanding dust should be avoided and if it settles on the skin then it should be washed off. After more extensive sanding operations a shower/bath and hair wash is advised.

APPLICABLE HAZARD & SAFETY PHRASES

Gurit produces a separate full Safety Data Sheet for all hazardous products. Please ensure that you have the correct SDS to hand for the materials you are using before commencing work.

LIGHT REFLECTIVE TECHNOLOGY (LRT)

Spabond 820HTA is formulated with Gurit's Light Reflective Technology included as standard which causes the resin or mixed system to fluoresce under UV light and can assist in developing best practise post work, to ensure minimum exposure and no transfer of epoxy outside the workshop, significantly reducing the risks of sensitisation and other conditions associated with contact with uncured resins. Contact Gurit Technical Support for further information.

PDS-Spabond820HTA-3-0921

SPABOND 820 RESIN & SPABOND 820HTA HARDENER

This product summary is intended for use in conjunction with further advice provided under the Instructions for Use section. All data has been generated from typical production material and does not constitute a product specification.

MIXING AND HANDLING

PROPERTY	UNITS	SP 820 RESIN	SP 820HTA HARDENER	MIXED SYSTEM	TEST METHOD
Appearance - colour	Description	White Blue		Light Blue	-
Appearance - form	Description		-		
Mix ratio by weight	Parts by weight	100 34		-	-
Mix ratio by volume	Parts by volume	100 38		-	-
Density at 21 °C	g/cm ³	1.34	1.19	1.30	Archimedes

COMPONENT & MIXED SYSTEM PROPERTIES

PROPERTY	UNITS	25°C	30°C	40°C	TEST METHOD
Spabond 820 Resin Viscosity	Р	110 - 150	80 - 110	50 - 80	-
Spabond 820HTA Hardener Viscosity	Р	30 - 45	30 - 40	30 - 40	-
Working Time at 34°C Tool Temperature (30 x 40mm bondline)*	hrs:min	01:30	-	-	-
Working Time at 40°C Tool Temperature (30 x 40mm bondline)*	hrs:min	01:04	-	-	-
Sag resistance*	mm		-		

ADHESIVE PERFORMANCE

MECHANICAL PROPERTIES	SYMBOL	UNITS	5 HOURS AT 70°C**	2 HOURS AT 70°C**	1 HOUR AT 80°C**	TEST STANDARD
Cleavage on steel	Fcleavage	kN	8.4	-	-	BS 5350 Part C1
Lap shear on steel	Tsteel	МРа	33.5	34.3	35.5	BS 5350 Part C5
Lap shear on epoxy GRP (8 plies epoxy infused YE600)	TEP-GRP	MPa	20.6	-	-	BS 5350 Part C5

THERMAL CURE PROGRESSION AT 70°C

CURE PROGRESSION (70°C)	SYMBOL	UNITS	1 HOUR	2 HOURS	3 HOURS	4 HOURS	5 HOURS	TEST STANDARD
Glass Transition Temperature	Tg ₂	°C	59.4	69.8	74.5	76.0	78.7	ISO 11357 (DSC)
Ultimate Glass Transition Temp	UTg ₂	°C	80.0				ISO 11357 (DSC)	

CURED MECHANICAL & THERMAL PROPERTIES

MECHANICAL PROPERTIES	SYMBOL	UNITS	2 HOURS AT 70°C**	1 HOUR AT 80°C**	TEST STANDARD
Glass Transition Temperature	Tg1	°C	78	71.0	ISO 6721 (DMA)
Tensile Strength	$\sigma_{\scriptscriptstyle T}$	MPa	66.0	65.9	ISO 527-2
Tensile Modulus	Eτ	GPa	4.70	4.63	ISO 527-2
Tensile Strain	Ет	%	3.20	2.86	ISO 527-2
3-point flexural strength	σ _F	N/mm²	113	114	ISO 178
3-point flexural modulus	E _F	GPa	4.7	4.8	ISO 178
3-point flexural strain	ε _F	%	3.6	3.4	ISO 178
Charpy (notched)	a _{cN}	kJ/m²	1.48	2.74	ISO 179-1
Fracture Toughness	K1C	MPa.m ^{0.5}	2.23	1.98	ASTM D5045

^{*}working time properties are highly subjective to ambient conditions and should be used as an approximate guideline for all Spabond systems
**cure schedule based on 2 hours at 20°C followed by a 1°C/min ramp to the specified cure temperature with a typical relative humidity of 50%



NOTICE

All advice, instruction or recommendation is given in good faith but the selling Gurit entity (the Company) only warrants that advice in writing is given with reasonable skill and care. No further duty or responsibility is accepted by the Company. All advice is given subject to the terms and conditions of sale (the Conditions) which are available on request from the Company or may be viewed at Gurit's Website: www.gurit.com/terms-and-conditions.aspx

The Company strongly recommends that Customers make test panels in the final process conditions and conduct appropriate testing of any goods or materials supplied by the Company prior to final use to ensure that they are suitable for the Customer's planned application. Such testing should include testing under conditions as close as possible to those to which the final component may be subjected. The Company specifically excludes any warranty of fitness for purpose of the goods other than as set out in writing by the Company. Due to the varied nature of end-use applications, the Company does, in particular, not warrant that the test panels in the final process conditions and/or the final component pass any fire standards.

The Company reserves the right to change specifications and prices without notice and Customers should satisfy themselves that information relied on by the Customer is that which is currently published by the Company on its website. Any queries may be addressed to the Technical Services Department.

Gurit is continuously reviewing and updating literature. Please ensure that you have the current version by contacting your sales contact and quoting the revision number in the bottom left-hand corner of this page.

TECHNICAL CONTACT INFORMATION

For all other enquiries such as technical queries:

Telephone + 44 1983 828000 (08:30 – 17:00 GMT)

Email technical.support@gurit.com

24-HOUR CHEMICAL EMERGENCY NUMBER

For advice on chemical emergencies, spillages, fires or exposures:

Europe +44 1273 289451 Americas +1 646 844 7309 APAC +65 3158 1412

E customer.support@gurit.com

W www.gurit.com

All trademarks used or mentioned in this document are protected by law.

PDS-Spabond820HTA-3-0921